City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/29/2009</u>
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S03WW_027MH	Test ID: <u>D1032-025007</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03WW_027MH
0			Water Level	
97.19999695			Dye Test Visible	@ TFA - downspout
97.80000305			Dye Test Visible	@ TFA - cleanout
97.90000153	10		Tap Factory Active	From 4107 Springdale
98			Manhole	S03WW_022MH
98			End of Survey	